

1




2

Step 2 : 50% tighten screw at this stage.







3

Step 3 : Atter all parts are in right position, then 100% tighten up all screws before using.



4



A	B	C	D	E
				
x4	x4	x4	x4	x1